







*Figure 1: Corroded hydraulic steering cutoff valve, improper wiring configuration, and rusted bottom plate.*



*Figure 2: Corroded steering gear ram foundation and rusted bottom plated.*



*Figure 20: Insufficient sealing causing stbd side shell to rust from improper window sealing.*



*Figure 19: Stanchion system showing substantial corrosion, rust, and paint chipping.*